

Version: 5.14.0.17525 Date: May 2018
(This version driver only support PID 0x0001)

New feature:

Remove all PCAP's PID from USB driver. Let the USB driver only supports single touch device.

Issue Fixed:

1. Fixed bug for if user contacts sensor and press "Add" button of utility for scan and add touch , the utility sometimes could not detect any touch device.
2. Fixed bug for USB driver's memory leak issue.

Known Problem:

The serial (COM) touchscreen may not work due to some Virtual Machine(for ex. VMware). This is because virtual machine may change serial port driver behaviors. To work around this problem, be sure to enable PnP function for serial port for EETI's driver.

Version: 5.14.0.17411 Date: APR. 2018

Issue Fixed:

1. Fixed bug for SAW device can not do firmware update issue.
2. Fixed bug for Draw test of the utility sometimes can not be executed.
3. Fixed bug for Saturn solution can not work issue.

Known Problem:

The serial (COM) touchscreen may not work due to some Virtual Machine(for ex. VMware). This is because virtual machine may change serial port driver behaviors. To work around this problem, be sure to enable PnP function for serial port for EETI's driver.

Version: 5.14.0.17302 Date: Mar. 2018

New feature:

USB driver supports wake up system from Hybrid mode sleep.

Issue Fixed:

Fixed bug for if user contacts sensor more than two points , the driver will report wrong mouse event.(USB and RS-232 driver for Multi-touch device)

Known Problem:

The serial (COM) touchscreen may not work due to some Virtual

Machine(for ex. VMware). This is because virtual machine may change serial port driver behaviors. To work around this problem, be sure to enable PnP function for serial port for EETI's driver.

Version: 5.14.0.16628 Date: Oct. 2017

New feature:

USB driver was passed Windows 10 RS3 certification.

Known Problem:

1. The serial (COM) touchscreen may not work due to some Virtual Machine(for ex. VMware). This is because virtual machine may change serial port driver behaviors. To work around this problem, be sure to enable PnP function for serial port for EETI's driver.

Version: 5.14.0.16628 Date: Aug. 2017

New feature:

Supports hardware flow control RS-232 interface devices.

Known Problem:

The serial (COM) touchscreen may not work due to some Virtual Machine(for ex. VMware). This is because virtual machine may change serial port driver behaviors. To work around this problem, be sure to enable PnP function for serial port for EETI's driver.

Version: 5.14.0.15315 Date: JUL. 2016

New feature:

Include Windows 7 and Windows 8.1/10 kernel driver in the one installation package.

Issue Fixed:

Update all kernel driver for use the new nonpage pool type NoPagedPoolNx for follow Windows new rule.

Known Problem:

The serial (COM) touchscreen may not work due to some Virtual Machine(for ex. VMware). This is because virtual machine may change serial port

driver behaviors. To work around this problem, be sure to enable PnP function for serial port for EETI's driver.

Version: 5.14.0.15116 Date: MAY. 2016

Issue Fixed:

Fixed issue for SAW can not to do firmware update.

Known Problem:

The serial (COM) touchscreen may not work due to some Virtual Machine(for ex. VMware). This is because virtual machine may change serial port driver behaviors. To work around this problem, be sure to enable PnP function for serial port for EETI's driver.

Version: 5.14.0.14916 Date: MAR. 2016

Issue Fixed:

Fixed issue for the xTouchMon(tray icon) cannot get registry values "ActiveChromeBtnDisplay" and "ButtonDisplay" form registry key [HKEY_CURRENT_USER\Software\eGalaxTouch].

Known Problem:

The serial (COM) touchscreen may not work due to some Virtual Machine(for ex. VMware). This is because virtual machine may change serial port driver behaviors. To work around this problem, be sure to enable PnP function for serial port for EETI's driver.

Version: 5.14.0.14608 Date: Dec. 2015

Issue Fixed:

Fixed issue for the USB touchscreen device cannot work immediately after completed driver package install.

Known Problem:

The serial (COM) touchscreen may not work due to some Virtual Machine(for ex. VMware). This is because virtual machine may change serial port driver behaviors. To work around this problem, be sure to enable PnP function for serial port for EETI's driver.

Version: 5.14.0.14231 Date: SEP. 2015

New feature:

UART driver passed HLK test for Windows 10 and got certificate.

Issue Fixed:

Fixed issue for the USB touchscreen driver cannot be installed after do Windows Update after 9/1.

Known Problem:

1. The serial (COM) touchscreen may not work due to some Virtual Machine(for ex. VMware). This is because virtual machine may change serial port driver behaviors. To work around this problem, be sure to enable PnP function for serial port for EETI's driver.

Version: 5.14.0.14205 Date: Aug. 2015

New feature:

USB driver passed HLK test for Windows 10 and got certificate.

Known Problem:

1. The serial (COM) touchscreen may not work due to some Virtual Machine(for ex. VMware). This is because virtual machine may change serial port driver behaviors. To work around this problem, be sure to enable PnP function for serial port for EETI's driver.